NO	Pic	Des	Size (MM)	Qty	Beam Seating Assembly Instructions	
1		Beam	95*1710	1	Helpful tip: Insert screws and turn a few revolutions only at each step. Do not fully tighten until all screws for each step are inserted. Tightening too soon can cause unevenness.	
2		Leg	606*88*300	2	Insert leveling glides into feet. Then attach legs	
3	į	Screw	M12*30	4	to the beam.	7 6
4	ڪ	Leveling Glide	70*30	4		
5		Leg Cap	38*48*20	4		
6	1	Bracket	332*35*278	6		<b>1</b> 0
7	9	Screw	M8*35	6		
8		Seat	520*417*624	3	First	
9	9	Screw	M8 <b>*</b> 30	18	To attach seats, attach at backrest first,	
10	a	Arm	343*80*262	2	then middle of seat, then the front of the seat with the screws provided	Next, attach the armrets in between the seats.
11	0	Beam Cap	95*1710	2	5	6
	7	Allen Wrench	6*6 mm	1		
	7	Allen Wrench	10*10 mm	1	The d	
		Torque Bar for Allen Wrench	12*120 mm	1	Add the caps on the beam and feet.	Adjust leveling glides as needed.